


## Rod The Welder Says...

- 1. Shield Eyes**
- 2. Wear Gloves**
- 3. Long Sleeve Shirt, Buttoned**
- 4. Safety Shoes**

**DO NOT LOOK AT GAUGES**  
**While Turning On Gas!**



**PROTECT OTHERS**  
**Shield Your Arc!**



**PROPERLY DISPOSE OF**  
**ROD STUBS!**

- Prevent burns
- Prevent falls

**Keep Welding Area**  
**Clean & Safe!**



Main Office: Cypress, Texas 77410

Phone: 281.807.0757 • Technical Hotline Phone: 1.800.980.2164 • [www.freedomalloys.com](http://www.freedomalloys.com)

**Freedom** **ALLOYS** Product • Welding Safety Seminars